

September 14, 2023

whom it may concern

NOF CORPORATION

Pipe Rupture Accident at Taketoyo Plant

At around 1:40 p.m. today, a pipe rupture accident occurred at Taketoyo Plant, Aichi Works of our company, and smoke was seen along with rupture noise and tremors. We are currently cooperating with the relevant authorities in their investigation of the site.

The following details are known as of 7:00 p.m. on Thursday, September 14.

1. location of occurrence

61-1, Aza Kitakomatsudani, Taketoyo-cho, Chita-gun, Aichi, Japan

NOF CORPORATION Aichi Works Taketoyo Plant, Piping to waste liquid storage tank

2. Date and time of occurrence

September 14, 2023 at approximately 1:40 p.m.

3. Damage (at present)

No injuries have been confirmed.

Physical damage Under investigation

4. causes and countermeasures

Although the authorities are still investigating the cause of the problem, we will do our utmost to investigate the cause. As soon as the cause is determined, we will take appropriate measures.

... and upwards

For inquiries regarding this matter, please contact

NOF CORPORATION

Corporate Communications Department

E-mail: info@nof.co.jp